



1-2	S 34°-07'-25" E,	243.30'
2-3	S 22°-45'-00" E,	320.43'
3-4	N 65°-27'-55" E,	340.80'
4-5	S 05°-36'-26" E,	511.50'
5-6	S 07°-01'-02" E,	295.50'
6-7	S 52°-43'-36" E,	328.00'
7-8	N 29°-21'-18" E,	537.50'
8-9	N 87°-21'-43" E,	95.80'
9-10	S 54°-51'-57" E,	785.21'
10-11	S 24°-31'-49" E,	579.03'
11-12	S 22°-31'-09" E,	380.19'
12-13	S 42°-31'-53" W,	725.73'
13-14	S 65°-02'-37" E,	289.74'
14-15	S 75°-35'-32" E,	289.08'
15-16	S 61°-34'-24" E,	597.94'
16-17	S 40°-02'-48" E,	33.66'
17-18	N 57°-35'-37" E,	396.60'
18-19	N 09°-34'-32" W,	491.70'
19-20	N 75°-57'-51" E,	456.72'
20-21	N 42°-19'-11" E,	610.38'
21-22	N 07°-10'-07" W,	971.77'
22-23	N 07°-11'-36" W,	339.15'
23-24	S 80°-32'-23" W,	102.70'
24-25	N 75°-51'-57" W,	42.60'
25-26	N 29°-24'-03" W,	108.20'
26-27	N 16°-38'-08" W,	120.40'
27-28	N 36°-34'-47" E,	89.25'
28-29	N 01°-15'-41" E,	120.80'
29-30	N 32°-00'-24" W,	75.00'
30-31	N 08°-45'-59" W,	93.90'
31-32	N 34°-11'-05" W,	141.10'
32-33	N 56°-15'-25" W,	292.30'
33-34	N 18°-36'-15" E,	90.50'
34-35	N 55°-21'-39" E,	114.20'
35-36	N 16°-17'-56" W,	75.97'
36-37	N 45°-27'-01" W,	187.80'
37-38	S 83°-26'-53" W,	103.90'
38-39	S 59°-45'-48" W,	130.40'
39-40	S 64°-11'-28" W,	91.40'
40-41	S 24°-13'-07" W,	143.30'
41-42	S 07°-37'-02" W,	60.75'
42-43	S 52°-39'-27" W,	109.70'
43-44	S 49°-27'-36" W,	131.80'
44-45	S 80°-15'-45" W,	171.00'
45-46	S 35°-05'-55" W,	148.30'
46-47	S 86°-20'-05" W,	143.30'
47-48	N 30°-48'-30" W,	146.60'
48-49	N 53°-05'-36" W,	176.20'
49-50	N 78°-56'-26" W,	114.90'
50-51	S 66°-03'-39" W,	182.05'
51-52	S 43°-26'-23" W,	93.60'
52-53	N 64°-02'-12" W,	265.95'
53-54	N 51°-38'-17" W,	235.80'
54-55	N 59°-34'-23" W,	230.30'
55-56	N 47°-08'-13" W,	243.78'
56-57	N 40°-01'-03" W,	94.15'
57-58	S 29°-38'-21" W,	566.65'
58-59	S 40°-33'-01" W,	509.15'
59-1	S 28°-01'-26" W,	241.10'



- CORNER DESCRIPTIONS**
- 1 Axis of fence corner recovered
 - 2 Spring leaf by rock, recovered
 - 3 Spring leaf of post in rock pit recovered
 - 4 Rock pile, recovered, iron pipe set
 - 5 Stake in victory stump hole, recovered. I. P. set
 - 6 Point in road
 - 7 Point in road
 - 8 Maple stump recovered, iron pipe set
 - 9 Iron axle, recovered
 - 10 30" Oak recovered, iron pipe set
 - 11 Rock recovered, iron pipe set
 - 12 10" Oak recovered, iron pipe set
 - 13 Point in road
 - 14 Iron pipe, set
 - 15 Iron pipe, set
 - 16 Iron axle, recovered
 - 17 Iron pipe, set
 - 18 Iron axle, recovered
 - 19 20" Ash recovered, iron pipe set
 - 20 12" Oak recovered, iron pipe set
 - 21 Iron pin in rock pile, recovered
 - 22 Concrete Mon. "G 257", recovered
 - 23 Concrete Mon. "G 267", recovered
 - 24-56 Points on creek
 - 57-59 Points on road

TOTAL ACRES	209.22
EXCEPTED ACRES	0.00
ROADS	2.13
UTILITY LINES	0.00
NET ACRES	207.09



TRACT NO. LI-52 & 53, BURTON AND RISH PLACE, IN THE 183RD DISTRICT G. M., LINCOLN COUNTY, GEORGIA PROPERTY OF MRS. T. W. CULLARS

FICKLEN AND ASSOCIATES			
ENGINEERS AND SURVEYORS			
WASHINGTON, GEORGIA			
SURVEY BY	W B F	DATE	10-3-60
DRAWN BY	W B F	DRAWING NO.	
CHECK BY	W B F	SCALE	1"=660'
			LI-1-52